

## 334 - 500X 1.4 Turbo MultiAir TCM Internal - Internal Watchdog Performance P1634-00

			Test results		
1	COMPONENT CONCERNED	CHECK USING DIAGNOSIS EQUIPMENT	OK (NO FAULTS DETECTED)	FAULT DETECTED	OPERATION
	Automatic transmission control unit	Connect the diagnosis equipment to the automatic transmission control module, delete the errors and check whether the error reappears when reproducing the conditions in which it appeared	End of diagnosis	The error reappears on the control unit	Go to Step 2
2	COMPONENT CONCERNED	AUTOMATIC TRANSMISSION CONTROL UNIT CHECK	OK (NO FAULTS DETECTED)	FAULT DETECTED	OPERATION
	Automatic transmission control unit	Check that the automatic transmission control unit is working correctly	End of diagnosis	Automatic transmission control unit not working correctly	Replace the automatic transmission control unit <b>Op. 2135B52 ELECTRONIC AUTOMATIC TRANSMISSION SYSTEM CONTROL UNIT - R.R.</b>