

Date	Result	Details
17/02/2023 15:49	Pass	Mileage: 123,240 miles + 3 miles travelled since last MOT.
10/02/2023 14:29	Fail	Mileage: 123,237 miles + 835 miles travelled since last MOT. Refusal Notices <ul style="list-style-type: none"> Emissions unable to be completed (8.2.1.2 (d)) - Major Front exhaust has a major leak of exhaust gases (6.1.2 (a)) - Major
14/01/2022 08:02	Pass	Mileage: 122,402 miles Advisory Notices <ul style="list-style-type: none"> Nearside rear brake pipe corroded, covered in grease or other material main pipe to hose corroded (1.1.11 (c)) Offside rear brake pipe corroded, covered in grease or other material main pipe to hose corroded (1.1.11 (c))
13/01/2022 10:22	Fail	Mileage: 122,402 miles + 10,038 miles travelled since last MOT. Refusal Notices

Date	Result	Details
		<ul style="list-style-type: none"> Central front oil leaking excessively from engine engine sump (8.4.1 (a) (i)) - Major Nearside front headlamp aim too high (4.1.2 (a)) - Major Offside front windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) - Major <p>Advisory Notices</p> <ul style="list-style-type: none"> Engine oil low no oil on dip stick Nearside rear brake pipe corroded, covered in grease or other material main pipe to hose corroded (1.1.11 (c)) Offside front service brake binding but not excessively (1.2.1 (f)) Offside rear brake pipe corroded, covered in grease or other material main pipe to hose corroded (1.1.11 (c))
26/01/2021 09:07	Pass	<p>Mileage: 112,364 miles + 5,621 miles travelled since last MOT.</p> <p>Advisory Notices</p> <ul style="list-style-type: none"> Engine sump heavy corrosion slight oil leak N/s/o/s front shocker tops slight play Nearside front lower arm rear bush slight play Nearside rear brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Date	Result	Details
		<ul style="list-style-type: none"> Nearside rear brake pipe corroded, covered in grease or other material main pipe corroded (1.1.11 (c)) Offside front brake pipe corroded, covered in grease or other material to hose corroded (1.1.11 (c)) Offside rear brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Offside rear brake pipe corroded, covered in grease or other material main pipe corroded (1.1.11 (c)) Under trays fitted obscuring some components
28/01/2020 10:03	Pass	<p>Mileage: 106,743 miles</p> <p>Advisory Notices</p> <ul style="list-style-type: none"> 2 rear shockers top bush have movement Covers /under trays Front brake disc have corrosion o/s/f & n/s/f N/s/f lower arm bush rear play Nearside tyre getting low on tread Nearside front low on inner side O/s/r brake pipe have corrosion Offside front tyre very low inner Rear hand brake cables have corrosion Sump has corrosion

Date	Result	Details
		<ul style="list-style-type: none"> Tracking may be out
28/01/2020 08:06	Fail	<p>Mileage: 106,743 miles + 15,567 miles travelled since last MOT.</p> <p>Refusal Notices</p> <ul style="list-style-type: none"> Central rear stop lamp(s) all not working (4.3.1 (a) (iii)) - Dangerous Offside front stop lamp(s) all not working (4.3.1 (a) (iii)) - Dangerous Nearside front windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) - Major Offside front headlamp aim too high (4.1.2 (a)) - Major Offside front windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) - Major <p>Advisory Notices</p> <ul style="list-style-type: none"> 2 rear shockers top bush have movement Covers /under trays Front brake disc have corrosion o/s/f & n/s/f N/s/f lower arm bush rear play Nearside tyre getting low on tread Nearside front low on inner side

Date	Result	Details
		<ul style="list-style-type: none"> • O/s/r brake pipe have corrsion • Offside front tyre very low inner • Rear hand brake cables have corrosion • Sump has corrosion • Tracking may be out
24/01/2019 10:05	Pass	Mileage: 91,176 miles + 22,839 miles travelled since last MOT. Advisory Notices
		<ul style="list-style-type: none"> • Nearside front brake disc worn, pitted or scored, but not seriously weakened inside face (1.1.14 (a) (ii)) • Offside front brake disc worn, pitted or scored, but not seriously weakened inside face (1.1.14 (a) (ii)) • Under trays fitted obscuring some components
19/01/2018 14:17	Pass	Mileage: 68,337 miles
19/01/2018 14:17	Fail	Mileage: 68,337 miles Refusal Notices

Date	Result	Details
------	--------	---------

- Nearside front position lamp(s) not working (1.1.a.3b)
- Nearside front tyre tread depth below requirements of 1.6mm (4.1.e.1)